
W GL Y GH B
FIELD WIRING TO WALL THERMOSTAT TERMINALS INDICATED
BLUE
BLUE
BLUE
HIGH FAN RELAY
NO
COM
COMPRESSOR RELAY
NO
COM
PURPLE
BLUE
GREEN
YELLOW
HEATER RELAY
NO
COM
BLACK
BLACK
NO
COM
LOW FAN RELAY
GRAY
RED
BLACK
PURPLE
WHITE
GRAY
WHITE
BLACK
PURPLE
ORANGE
WHITE
WHITE
HEATER
BLUE
ORANGE
LIMIT SWITCH
WHT
GRN
WHT
9 8 7 6 5 4 3 2 1
HIGH VOLTAGE AC SUPPLY WIRING
PLUG CONNECTS TO UPPER UNIT. SEE DIAGRAM SUPPLIED WITH UPPER UNIT FOR ADDITIONAL WIRING.
1976B171