



REPAIR PARTS LIST


FOR

7530-736, 7530A736

FLUSH MOUNT HEAT PUMP

CEILING PLENUM

7530-736
7530A736





7530-736
7530A736

CODE	MODEL USED ON	PART NUMBER	DESCRIPTION	NO. REQ.
1.	All	6798-3701	Divider Air Seal	1
2.	All	7330-102	Divider	1
	All	7330-105	Divider (Adjustable - Short)	1
	All	7330-1081	Divider (Adjustable - Tall)	1
3.	All	7330B361	Divider Insulation	1
4.	All	7330-3621	Angle Air Seal (2)	1
5.	All	7330A550	Air Chute Weld Assembly	1
6.	All	7330B360	Insulation - Tray	1
7.	All	7530-508	Junction Box Assembly Complete	1
8.	All	7530A340	Plug Assembly	1
9.	All	7530A340	Plug Assembly	1
10.	All	7530B320	Terminal Board	1
11.	All	7330A365	Isolator Blank	1
12.	All	7330A3311	P.C. Board	1
13.	All	7330A104	Junction Box Lid	1
14.	All	6798A3761	Filter	1
15.	All	6798-3041	Grille (Plastic - Ivory)	1
16.	All	7330-6161	Small Parts Pkg. (Includes Coil Sensor Freeze/Limit Combination)	1
17.	All	1460-5031	Limit Switch	1
18.	All	7332-3551	Heat Element	1
19.	All	7332-511	Heat Assembly Wiring Harness	1
20.	All	7332-4551	Heater Assembly	1
ns	All	7330B3631	Basepan Gasket (Shipped Loose)	1
ns	All	6798A368	Insulation - 1/8" (Shipped Loose)	1

ns = not shown