



REPAIR PARTS LIST

FOR

6636 “-,A,B,C” SERIES

HIGH EFFICIENCY

PACKAGED AIR CONDITIONERS

RV Products
A Division of Airxcel, Inc.
P.O. Box 4020
Wichita, KS 67204

6636 “-,A,B,C” SERIES



| CODE | USED ON MODEL | PART NUMBER | DESCRIPTION | NO. REQ. |
|------|------------------|----------------|---|-------------|
| 1. | “-” | 6636-511 | Basepan Assembly With Insulation | 1 |
| | “A” | 6535A511 | Basepan Assembly With Insulation | 1 |
| | “B, C” | 6535B511 | Basepan Assembly With Insulation | 1 |
| 2. | “-” | 6636-502 | Top With Insulation | 1 |
| | “A” | 6535A502 | Top With Insulation | 1 |
| 3. | All | 6636-144 | Side Panel Right | 1 |
| 4. | “-” | 6636-519 | Bulkhead With Insulation | 1 |
| | “A” | 6535-519 | Bulkhead With Insulation | 1 |
| | “B” | 6535A519 | Bulkhead With Insulation | 1 |
| 5. | All | 6636-140 | Lower Filler Panel | 1 |
| 6. | “-” | 6636-545 | Blower Door Assembly | 1 |
| | “A” | 6535A545 | Blower Door Assembly | 1 |
| 7. | All | 6636A341 | Filler Panel | 1 |
| 8. | All | 6636-115 | Tube Bracket | 1 |
| 9. | All | 6535-548 | Access Door | 1 |
| 10. | “-” & “A” | 6636-530 | Electric Panel Assembly | 1 |
| | “B” | 6636A530 | Electric Panel Assembly | 1 |
| 11. | All | 6636-111 | Divider Shelf | 1 |
| 12. | All | 6795-117 | High Voltage Isolator | 1 |
| 13. | All | 6535B346 | Electric Box Door | 1 |
| 14. | All | 1452A1541 | Condenser Coil | 1 |
| 15. | All | 1452B1531 | Evaporator Coil | 1 |
| 16. | All | 6636A104 | Drain Pan | 1 |
| 17. | All | 6795-200 | Drain Valve | 1 |
| 18. | All | 1450A2119 | Compressor | 2 |
| 19. | All | 1450-0071 | Overload (MRA #2753-117) | 2 |
| 20. | All | 6759-3081 | Compressor Foot Pkg. (3/Pkg.) | 2 |
| 21. | All | 6636B131 | CKT #1 Suction Line Assembly Coil | 1 |
| 22. | All | 6636B129 | CKT #2 Suction Line Assembly Coil | 1 |
| 23. | All | 6636-126 | CKT #1 Discharge Line Assembly | 1 |
| 24. | All | 6636-125 | CKT #2 Discharge Line Assembly | 1 |
| 25. | All | 6636-130 | CKT #1 Suction Line Assy. Compressor | 1 |
| 26. | All | 6636-520 | Liquid Line Assembly - Complete | 2 |
| 27. | All | 6536A515 | O.D. Blower Housing | 1 |
| 28. | All | 1472-1161 | O.D. Blower Wheel | 1 |
| 29. | All | 6795A150 | O.D. Blower Venturi | 2 |
| 30. | All | 6795B313 | Safety Screen | 1 |
| 31. | All | 6795A3011 | O.D. Blower Motor Mount | 1 |
| 32. | All | 6795A3031 | Sleeve/Grommet Pkg. (4/Pkg.) | 2 |
| 33. | All | 1468A3029 | O.D. Blower Motor | 1 |
| 34. | All | 1499-5631 | O.D. Blower Capacitor (12.5 Mfd/370V) | 1 |
| 35. | All | 1499-951 | Rubber Capacitor Boot | 1 |
| 36. | All | 6536-514 | O.D. Bearing Bracket (Blower) | 1 |
| 37. | All | 6536-3011 | Pillow Block Bearing (I.D. or O.D.) | 1 |
| 38. | “-” | 1472-1001 | I.D. Blower Wheel | 1 |
| | A,B,C | 1472-1151 | I.D. Blower Wheel | 1 |
| 39. | “-” | 6795-151 | I.D. Blower Venturi | 1 |
| | “A” | 6535-287 | I.D. Blower Venturi | 1 |
| 40. | All | 6795A3021 | I.D. Blower Motor Mount | 1 |



6636 “-,A,B,C” SERIES

| CODE | USED ON MODEL | PART NUMBER | DESCRIPTION | NO. REQ. |
|------|------------------|----------------|--|-------------|
| 41. | “-” | 1468A3129 | I.D. Blower Motor | 1 |
| | “A” | 1468-3219 | I.D. Blower Motor | 1 |
| | “B,C” | 1468A3219 | I.D. Blower Motor | 1 |
| 42. | “-” | 6636-589 | I.D. Blower Housing | 1 |
| | “A” | 6535-589 | I.D. Blower Housing | 1 |
| | “B,C” | 6535C589 | I.D. Blower Housing | 1 |
| 43. | “-” | 6636-288 | Indoor Blower Cut Off | 1 |
| | “A” | N/A | | |
| 44. | All | 7330A3231 | Freeze Switch | 1 |
| 45. | All | 1460-1131 | Compressor Relay | 2 |
| 46. | All | 1499-5671 | Compressor Run Capacitor (30 Mfd/370V) | 1 |
| 47. | All | 6795-3151 | High Voltage Terminal Board | 1 |
| 48. | All | 1216-228 | Grounding Lug | 2 |
| 49. | All | 8333A9021 | Start Device | 1 |
| 50. | All | See #50 | Start Device | 1 |
| 51. | All | 6636A3209 | P.C. Board Kit | 1 |
| 52. | All | 1499-5461 | I.D. Blower Capacitor (7.5 Mfd/370V) | 1 |
| ns | “-” & “A” | 6535-5081 | Replacement Fuse Outdoor Fan | 1 |

Note: All parts with three digit suffix numbers are “Special Order” Parts. These parts are subject to factory availability and require extra time for delivery.

Note: “A” Model units have new higher capacity indoor blower assembly.

6636 “-,A,B,C” SERIES

