



**REPAIR PARTS LIST
FOR
8530A731
HEAT PUMP STRAIGHT THRU
DUCT CEILING PLENUM**

CODE	USED ON MODEL	PART NUMBER	DESCRIPTION	NO. REQ.
1.	All	8333-1031	Mounting Frame & Bolt Pkg.	1
2.	All	8330-552	Duct Assembly	1
3.	All	8330-3571	Duct Divider	1
4.	All	8330-101	Duct Plate	1
5.	All	6798A3761	Filter	1
6.	All	6798-3041	Grille (Plastic)	1
7.	All	7330A3231	Coil Sensor	1
8.	All	8330-5091	Junction Box Complete	1

ns = not shown

SPECIAL ORDER PARTS:

Note: All parts with three digit suffix numbers are “Special Order” Parts. These parts are subject to factory availability and require extra time for delivery.

**RV Products
A Division of Airxcel, Inc.
P.O. Box 4020
Wichita, KS 67204**

