



REPAIR PARTS LIST

FOR

8530B7332


FLUSH MOUNT HEAT PUMP

CEILING PLENUM

NO HEAT STRIP/NO DIVIDER

**RV Products
A Division of Airxcel, Inc.
P.O. Box 4020
Wichita, KS 67204**

8530B7332





8530B7332

CODE	MODEL USED ON	PART NUMBER	DESCRIPTION	NO. REQ.
1.	All	9233A5251	Mounting Frame & Bolt Pkg.	1
2.	All	8330-101	Duct Plate	1
3.	All	8530-5091	Junction Box Assembly	1
4.	All	6798A3761	Filter	1
5.	All	6798-3041	Grille (Plastic)	1
6.	All	8330A595	Small Parts Pkg.	1
ns.	All	7330A3231	Coil Sensor	1

SPECIAL ORDER ITEMS

Note: All parts with three digit suffix numbers are “Special Order” Parts. These parts are subject to factory availability and require extra time for delivery.

ns = not shown